

H ↑

HRP 3232   HRP 5040   HRP 5050   HRP 8050   HRP 10080

— 50 Hz   — 60 Hz

- ganz gedrosselten Zustand vermeiden
- fully throttled condition to be avoided
- Evite un estrangamiento total
- Debe evitarse un estrangamiento total

